

KB173966798: Hotfix1402109 for i-cut Layout 14.0.1

Summary

Export cutting data shows open cut paths.

Symptoms

Small gaps in the cut path.

More Information

For installation instructions and to download the hotfix, go to <https://mysoftware.esko.com/Hotfixes/Details/1402109/14.0.1>.

Article information	
Applies to	i-cut Layout 14.0.1
Created	17-Nov-15
Last revised	
Author	MRAN
Case Number	429325

Contents

- [Summary](#)
- [Symptoms](#)
- [More Information](#)

What is a Hotfix?

A Hotfix is a software package that you can install on an existing installation of our software. Each hotfix contains fixes for one or more known issues in our released software.

Because there is always a small chance for a hotfix to cause new issues, you should only install Recommended Hotfixes, unless otherwise instructed by your Esko Software Support team.